NEW

A Futura new SW version is available

Vers. 2.1.8 db 1.09

Proceed with the following operations on the Futura machine according to the previous software versions that was installed:

Please refer to the machine manual for the operations to follow

Futura Software Version	Reload APP Silca.apk	Reload APP SilcaKeyboard.apk	Optical reader calibration	Zero-point calibration (standard flat key)	Calibration Clamp Standard key	Clear the cache in the applications Silca
2.0.1	No	No	No	No	No	Yes
2.0	No	No	No	No	No	Yes
1.13	No	No	No	No	No	Yes
1.12	No	No	No	No	No	Yes
1.10	Yes	Yes	No	No	No	Yes
1.6	Yes	Yes	No	No	No	Yes
1.0	Yes	Yes	Yes	Yes	Yes	Yes

Look below for news about the Futura SW Update

Copyright by Silca S.p.A.-All right reserved

FUTURA NEWS WEB

NEW

June 2014 — 1_2014 FUTURA v. 2.1.8

Futura Programs	New system	
	Data update with new series. • GERDA (WKM3; WKM1) • CORBIN (Evolution) • LINCE (C4;C2) • MAUER (MLS) • ISEO (CSR R9 Country N; Plus N) • TESA • KESO (2000S;4000S) • KABA (Titan; 8S-14 Mixed) • YALE • ABUS (NW52;NW72)	• AGB (5000) • GERA (WS; WSG; 2000 Plus) • IFAM • VIRO • MOTTURA (C43) • BASI (CX6 Left) • ESETY (Omega) • ANKERSLOT (Infinity / Multi) • HUGO (GR 2.55)
Futura Programs	**New function**	
	• Decoding and copying using read measurements • Management of more jaws for the same data card	
Futura Programs	**Bug Fixed**	
Bug fixed	• Corrected a decoding problem related to some dimple keys • Solved the problem related to search of some data card	

Copyright by Silca S.p.A.-All right reserved

May 2014 — 1_2014 FUTURA v. 2.0.1

Futura Programs	Bug Fixed
Bug fixed	• Solved the problem of password enabling for some data cards

Copyright by Silca S.p.A.-All right reserved

FUTURA NEWS WEB

May 2014 **1_2014 FUTURA v. 2.0.0**

Futura Programs	New function
	• Management of comparatives and alternatives key • Option to select the key manufacturer • Option to detect key blank measurement before cutting edge keys
Futura Programs	**Bug Fixed**
Bug fixed	• Communication problem • Copy a Simplex Key (by card) • Error in decoding dimple key (false contact and broken tracer) • Improved accuracy and performance of copy by original

Copyright by Silca S.p.A.-All right reserved